



I Own a 3M Speedglas 9100 FX Air. How do I upgrade to the NEW Speedglas G5-01 Welding Helmet?

Upgrade from FX Air to G5-01

By now you've likely heard about the new 3M Speedglas Heavy Duty Respiratory Welding Helmet G5-01. If you are one of the tens of thousands of Australian or Kiwi welders who own a 3M Speedglas 9100 FX Air and would like to upgrade to the new 3M Speedglas G5-01 Welding Helmet, you have TWO options:

1. Keep your Adflo PAPR and Upgrade Your Head-Top Only

The most economical way to upgrade to the new 3M Speedglas G5-01 Welding Helmet is by hanging onto your existing Adflo PAPR and simply upgrading your head-top. The 3M Speedglas G5-01 Upgrade Kit comes with the new 3M Speedglas G5-01 Flip-Up Welding Helmet and the new Speedglas G5-01 Welding Lens with True-View and Variable Colour. Simply attach the helmet to your existing Adflo PAPR and you can benefit from all the features of the New 3M Speedglas G5-01 Welding Helmet including climate control, larger welding lens with a shade 14, larger grinding visor, narrow more streamlined design, TrueView and Variable Colour, Bluetooth Connectivity and a number of configurable extra protection and lighting options.

2. Upgrade Your Complete System

The second option is obviously to upgrade your complete kit. The new 3M Speedglas G5-01 comes with a heavy-duty Adflo PAPR which gives you approximately 12 hours of battery life. If you'd like to take advantage of the configurable task light then we recommend this heavy duty battery option, as the task light draws its power from the Adflo battery. The complete kit also comes with the new 3M Speedglas Heavy-Duty Carry Bag to protect the welding helmet and respiratory system in between uses.

[To Upgrade Your Speedglas FX Air Click Here](#)

Contacts

David Chippendale
02 94390111
[mailto: davidc@awsi.com.au](mailto:davidc@awsi.com.au)